

VISIT...

LANZAROTE
Caliente.COM



stereoscopic



stereoscopic



Sensors used in well CWL D3 (unsaturated zone):
pressure transducer, chemiresistor, humidity sensor,
T-type thermocouple (not shown)




Deploying the sensors in well CWL D3 (CWL in background)

Sensors used in well
CWL MW2BL
(saturated zone):
chemiresistor (top),
submersible pressure
transducer, T-type
thermocouple (not
shown)



Deploying sensors in well CWL MW2BL (~150 m
or 500 ft to the water table)

sensors



sensors